

Message Text

LIMITED OFFICIAL USE

PAGE 01 MANILA 14832 200155Z
ACTION SY-05

INFO OCT-01 EA-10 ISO-00 SYE-00 /016 W
-----032470 200202Z /66
P R 200109Z SEP 77
FM AMEMBASSY MANILA
TO SECSTATE WASHDC PRIORITY 5347
INFO AMCONSUL HONG KONG

LIMITED OFFICIAL USE MANILA 14832

HONG KONG FOR TRC, RSS

E.O. 11652: NA
TAGS: ASEC, AFSP
SUBJECT: SECURITY LIGHTING AND PHYSICAL SECURITY IMPROVEMENTS
AMBASSADOR EDMOND'S RESIDENCE

REF: STATE 211441

1. DETAILED COST BREAKDOWN OF SECURITY IMPROVEMENTS
RECOMMENDED BY RSO SURVEY FOR SUBJECT RESIDENCE FOLLOW:

A. DUE TO THE HOUSE'S EXPOSED LOCATION AND NEW CON-
STRUCTION ON THE WEST SIDE, THE PRESENT 159 FT. LENGTH
OF LOW STONE WALL SHOULD BE RAISED WITH 6 FT. CHAIN
LINK TO AN OVERALL HEIGHT OF 10 FEET. ESTIMATED COST
FOR LABOR AND MATERIALS \$1,750.00

B. AN ORNATE BLOCK FENCE DEFINING THE PERIMETER IN
FRONT OF THE HOUSE SHOULD BE ERECTED SINCE THE
PRESENT SITUATION IS UNTENABLE. THERE IS NO BARRIER
BETWEEN THE DINING ROOM AND THE STREET BUT A SHORT DIS-
TANCE OF LAWN AND A PLATE GLASS WINDOW, THEREFORE,
A WALL SHOULD BE CONSTRUCTED WHICH AT A MINIMUM WILL
DEFINE THE PERIMETER AND FORCE A WOULD-BE INTRUDER TO
LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 02 MANILA 14832 200155Z

MAKE THE ILLEGAL ACT OF CLIMBING THE WALL. ESTIMATED
COST FOR LABOR AND MATERIALS \$300.00

C. THE LOW 149 FT. WALL ON THE EAST PERIMETER SHOULD BE
RAISED AN ADDITIONAL 4 FEET. THIS SHOULD BE OF CONCRETE
BLOCK CONSTRUCTION AND MUST BE CONSISTENT WITH THE
PRESENT WALL AND SHRUBBERY ON THE EAST SIDE OF THE

PERIMETER. COST FOR LABOR AND MATERIALS \$800.00

D. THERE ARE PRESENTLY TOO MANY DARK SPOTS IN THE REAR AREA OF THE RESIDENCE. FIFTEEN (15) ADDITIONAL OUTDOOR LIGHT FIXTURES AND BULBS WOULD BE REQUIRED AT THE VARIOUS CORNERS OF THE HOUSE AND IN THE REAR AREA SHRUBBERY. COST FOR WIRING MATERIALS, FIXTURES, AND NEW ELECTRICAL SERVICE TO THE SECURITY LIGHTS \$500.00

E. THE REAR BEDROOM WINDOWS, KITCHEN AREA, AND SERVANTS' AREA ARE EXPOSED TO SURREPTITIOUS ENTRY. THESE WINDOWS SHOULD BE GRILLED WITH 3/8" STEEL BARS. ESTIMATED COST OF INSTALLATION AND MATERIALS \$1,100.00

2. BECAUSE OF EXTENSIVE CONSTRUCTION IN AREAS SURROUNDING AMBASSADOR EDMOND'S RESIDENCE, COUPLED WITH RSO'S ANALYSIS OF LOCAL THREAT IN SURROUNDING NEIGHBORHOOD AND LOCATION OF RESIDENCE, RSO FEELS THAT THE ABOVE MEASURES ARE THE MINIMUM REQUIRED TO INSURE A SECURE ENVIRONMENT FOR THE HIGHLY VISIBLE U.S. AMBASSADOR TO THE ASIAN DEVELOPMENT BANK.
DECONTROL 10/1/77.
STULL

LIMITED OFFICIAL USE

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01-Jan-1994 12:00:00 am
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Sent Date: 20-Sep-1977 12:00:00 am
Decaption Date: 01-Jan-1960 12:00:00 am
Decaption Note:
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 22 May 2009
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1977MANILA14832
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Expiration:
Film Number: D770340-0989
Format: TEL
From: MANILA
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1977/newtext/t19770944/aaaablca.tel
Line Count: 85
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: 009c0a42-c288-dd11-92da-001cc4696bcc
Office: ACTION SY
Original Classification: LIMITED OFFICIAL USE
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: LIMITED OFFICIAL USE
Previous Handling Restrictions: n/a
Reference: 77 STATE 211441
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 23-Feb-2005 12:00:00 am
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 1209348
Secure: OPEN
Status: NATIVE
Subject: SECURITY LIGHTING AND PHYSICAL SECURITY IMPROVEMENTS AMBASSADOR EDMOND'S RESIDENCE
TAGS: ASEC, AFSP
To: STATE
Type: TE
vdkgvwkey: odbc://SAS/SAS.dbo.SAS_Docs/009c0a42-c288-dd11-92da-001cc4696bcc
Review Markings:
Margaret P. Grafeld
Declassified/Released
US Department of State
EO Systematic Review
22 May 2009
Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 22 May 2009